Division of Health Care Facilities

PRINTED: 02/26/2016 FORM APPROVED

(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING; 01 - MAIN BUILDING 01 TN3101 02/23/2016 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 26 SECOND STREET BRIDGE AT MONTEAGLE (THE) MONTEAGLE, TN 37356 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (Xå) COMPLETE (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) PREFIX (EACH CORRECTIVE ACTION SHOULD BE PREFIX DATE TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY) K 062 CONT: 1200-8-6-.09(1) Life Safety N 901 comparing with Life Safety Codes to ensure new (1) Any hursing home which complies with the regulations, if any, are being met. required applicable building and fire safety c. Any findings that are not compliant with Life regulations at the time the board adopts new Safety Codes will be reported to the Administrator codes or regulations will, so long as such Immediately for correction along with reporting to compliance is maintained (either with or without the Quality Assurance committee monthly. waivers of specific provisions), be considered to be in compliance with the requirements of the 1200-8-6-.09 (1) Life Safety new codes or regulations. N 901 (1) Any nursing home which complies with the required applicable building and fire safety regulations at the time the board adopts new This Rule is not met as evidenced by: codes or regulations will, so long as such Based on observations and testing, the facility compliance is maintained (either with or failed to comply with applicable building and fire without waivers of specific provisions), be safety regulations. considered to be in compliance with the The finding included: requirements of the new codes or regulations. Observation and testing on 2/23/2016 at 9:34 AM, Corrective Action: 2/23/2016 revealed locking arrangement (slide lock bar) that 1) Residents Affected: requires effort to unlock the door in the women's a. No resident(s) were affected by deficient restrooms. National Fire Protection Association (NFPA) 101, 8.3.3.2.3 (2012 Edition) practice. Not Resident Specific. 2) Identify: This finding was verified by the maintenance 100% audit was completed on 2/26/2016 by the director and the administrator during the exit Maintenance Director to make sure all locks were conference on 2/23/2016. in good working condition. 3) Measures: The Maintenance Director was in-serviced on 2/26/2016 on proper working locking devices on doors. An In-service will be completed with staff on notifying the Maintenance Director of any issues with locks not working properly. The Maintenance Director will audit and test manual locks monthly x 3 months and then quarterly thereafter. Any issues with locks not working will be reported to the Maintenance Director immediately. Division of Health Care Facilities LABORATORY DIRECTORS OR PROVIDED SUPPLIER REPRESENTATIVE'S SIGNATURE